

## *SCAN METHOD FOR BUILT-IN-SELF-REPAIR (BISR)*

### ABSTRACT

A system and method for protecting the values stored in a BISR repair block and, optionally, debugging the BISR repair logic without altering normal test flow is implemented by a circuit comprising a plurality of soft latches within the BISR repair block, the soft latches being coupled together to form a BISR scan chain for holding BISR repair information. A chip level scan enable signal for enabling a scan test and a scan hold control signal for controlling holding of the repair information in the soft latches of the BISR scan chain is provided to the circuit. The chip level scan enable signal and the scan hold control signal cooperate to control connection of the BISR scan chain to other scan chains during a scan test, so that the BISR repair information is held within the soft latches. A diagnose enable signal may likewise be provided. The diagnose enable signal cooperating with the chip level scan enable signal and the scan hold control signal for enabling debugging of logic connecting the BISR scan chains.

09880675-061304  
TOP SECRET

## Patent Assignment Abstract of Title

### Total Assignments: 1

**Application #:** 09880675

**Filing Dt:** 06/13/2001

**Patent #:** NONE

**Issue Dt:**

**PCT #:** NONE

**Publication #:** NONE

**Pub Dt:**

**Inventors:** Ghasi R. Agrawal, Mukesh K. Puri

**Title:** Scan method for built-in-self-repair (BISR)

### Assignment: 1

**Reel/Frame:** 011926/0174

**Received:**  
06/28/2001

**Recorded:**  
06/13/2001

**Mailed:**  
09/05/2001

**Pages:** 4

**Conveyance:** ASSIGNMENT OF ASSIGNORS INTEREST (SEE DOCUMENT FOR DETAILS).

**Assignors:** AGRAWAL, GHASI R.

**Exec Dt:** 06/13/2001

PURI, MUKESH K.

**Exec Dt:** 06/13/2001

**Assignee:** LSI LOGIC CORPORATION

1551 MCCARTHY BLVD.

MILPITAS, CALIFORNIA 95035

**Correspondent:** LSI LOGIC CORPORATION

PETER P. SCOTT

INTELLECTUAL PROPERTY LAW DEPARTMENT

1551 MCCARTHY BLVD.

MILPITAS, CA 95035

Search Results as of: 3/4/2004 10:58:22 A.M.

If you have any comments or questions concerning the data displayed, contact OPR / Assignments at 703-308-9723  
Web interface last modified: Oct. 5, 2002